



LOGGING INDUSTRY  
SERIES

# Skidder Backs into Forester's Truck

One fall day last year a forester arrived at a logging contractor's operation with his job instructions for that particular tract of timber. Upon his arrival, he noticed several logging crew members working on a skidder. He knew that the information he needed to deliver to the logging contractor would only take a few minutes, so the forester parked his truck approximately 100 feet behind the skidder. As the forester and logging contractor talked about the contract, the skidder operator started the skidder and put it in reverse. Not observing the truck parked behind him, the skidder operator hit the front of the forester's truck with the grapple and rear tire of the skidder causing \$7,000.00 in damages to the truck. Fortunately, there were no injuries in this accident.

None of the people involved in this incident were new to logging. The 45-year-old forester had 17 years of injury-free employment and had been fully trained in logging safety. The skidder operator had 15 years of logging experience, and his "master logger" certification.

## Discuss With Your Crew

- When visiting a logging operation, be aware of designated parking areas.
- Never assume the equipment operator is aware of or can see what is behind him at all times while in the equipment.
- Equipment operators should perform a walk-around inspection before operating equipment, to ensure there are no objects or persons close to or behind the equipment.



# Skidder Retrocede en Camión

En un día de caída en el sur, un guardabosques llegó en una la operación de contratista que apunta con sus instrucciones de trabajo en ese trato particular de madera. Sobre su llegada, él advirtió a varios miembros de tripulación que apuntan que trabaja en un skidder. Supo la información que debió entregar al contratista que apunta sólo tomaría unos minutos, así que el guardabosques estacionó su camión aproximadamente 100 pies detrás del skidder. El de 45 años de edad guardabosques tiene 17 años de herida libertan empleo, y habían sido entrenado completamente a apuntar la seguridad. El operario de skidder tiene 15 años que apuntan experiencia, y el suyo certificación "magistral de leñador" e instrucción fueron actuales. Como el guardabosques y apuntar a contratista habló del contrato, el operario de skidder comenzó el skidder, lo puso en revés, y no observando el camión estacionado detrás del skidder, golpeó la frente del camión con la lucha y llanta trasera del skidder, causando \$7.000,00 en daños al camión. No había heridas en este accidente.

## Discuta Con Su Tripulación

- Al visitar una operación que apunta, está consciente de designado estacionando áreas.
- Nunca asume que el operario de equipo está consciente de o puede ver lo que está detrás de él siempre mientras en el equipo.
- Operarios de Equipo deben realizar una caminata alrededor de inspección antes de operar equipo, para asegurar que no hay objetos ni personas cercano a ni detrás del equipo.